

Search over 57,700 items for sale...

Search

Browse by category ▼

Auctions ▼

How it works ▼

Financing

Home Page / Trucks & Trailers / Humvees / 2 Door Soft Top w/Truck Body

[Search for other Humvees items](#)



AM General M1025 HMMWV 2 Door Soft Top w/Truck Body

ITEM NUMBER	1568157
LOCATION	Yermo, California, United States. 92398
SOLD ON	8/22/18
WINNING BID	US \$10,100
# OF BIDS	46 View Bid History

SOLD!

ITEM DETAILS

MILEAGE	17,531 Miles
VIN	116XXX

6.2L Diesel Engine, Automatic Transmission, 4x4, 8,200 lb. GVWR, 2 Door, Soft Top, Cargo Cover, Cargo Cover Bows, Armament Carrier Body, 37x12.50R16.5 Tires. ***Buyer will need to complete and submit a Hold Harmless Agreement before scheduling pickup.***No further demilitarization is required. The HMMWV is available for pick up as shown.***Please see DLA supplied Tire Safety Warning document below.***



Inspected by IronPlanet.

Your purchase is protected by our **IronClad Assurance**.



[See Full Gallery](#) (45 - photos & videos)

[Print](#)
[Email](#)
[Shar](#)
[Shar](#)
[Shar](#)

Recommendations For You [Search all](#)



**GM 6.2L Diesel Engine
w/Container**
Pennsylvania (89 mi away)
US \$5.00



**2013 Magnum MEG30I/ISO
DRASH Shelter Transport**
North Carolina (267 mi away)
US \$3,500



**2013 Magnum MEG30I/ISO
DRASH Shelter Transport**
North Carolina (267 mi away)
US \$3,500



**2014 Magnum MEG30I/ISO
DRASH Shelter Transport**
North Carolina (267 mi away)
US \$3,500



**Rock Island Arsenal CMTH
Contact Maintenance Shelter**
Alabama (812 mi away)
US \$500



2013 GEM EL Utility V
California (2,187 mi aw)
US \$300

Previously Viewed



**2003 AM General M1045A2
HMMWV 4 Door Hard Top**
Georgia (622 mi away)
US \$35,700

INSPECTION REPORT

General Appearance
Drivetrain

Control Station
Chassis

Engine
Logistics

Please note that as the buyer, you are responsible for reviewing the entire inspection report when evaluating an item.

IMPORTANT INFORMATION

Export Control Compliance
Documentation
Shipping & Pick Up Details


Manifest
Payment Details
Questions

 Protected by IronClad Assurance®

GENERAL APPEARANCE

DESCRIPTION	RATING	DETAILS
Paint		
Sheet Metal Condition		
Steps		
Grab Rails		
Mirrors		
Exterior Lights		Not operational 
 (5)		

CONTROL STATION



NOTICES & RESTRICTIONS

This item is offered for **Off-Road Use Only**.

Buyer will be required to sign a **Hold Harmless Agreement**.

Buyer is required to submit an End-Use Certificate (EUC) to be reviewed prior to removal of the item. First-time buyers of Demil B,D,E,F,Q, OR C items may experience an extended review period in the Trade Securities approval process.

GovPlanet is only permitted to sell Demil B,D,E,F,Q, OR C items within the United States and only to U.S. citizens.


Security requirements and restrictions may apply at the time of pickup. **See shipping terms for details.**

Specific terms & conditions apply. **See details.**

Items may be subject to U.S. export controls. **See details.**












MANIFEST

NSN/LSN	Demil code ¹	Description (DTID) 
2320011077155	Q	SZ31296298D001

¹DLA Disposition Services Demilitarization Codes. Click on code for more information.



DOCUMENTATION

DESCRIPTION	RATING	DETAILS
Glass Condition		No visible damage
Seating		
Seat Belts		Operational
Steering Control		
Drivetrain Controls		
Master Cylinder/Brake Control		
Park Brake		Stopped the vehicle while rolling
Limited Function Check - Brakes		The brake system functioned, stopping and holding the machine.
Oil Pressure		32 PSI 
Warning Lights		Operational 
Gauges		Some not operational 
Odometer		17,531 Miles - IronPlanet makes no guarantees as to actual hours/miles; we can only report what can be visually observed. 
Heater		Operational
Limited Function Check		The main components are in place and operational as noted.
 (13)		
ENGINE		

**TIRE SAFETY
WARNING**



PAYMENT DETAILS

- Within **3 business days** after the auction, the buyer must submit full payment, including applicable taxes and fees to avoid **late fees**. For this item, payment is due on or before August 27.
- This item is subject to **California sales tax**.
- Buyer must pay a **transaction fee**, based on the final selling price:

FINAL SELLING PRICE

Above \$1

TRANSACTION FEE

10%

- Payment can be made by **wire transfer (recommended)** or credit card (**additional fee will apply**).
- If Selected, a Standard Form 97 (SF97) or Transferable titling document will be sent to the buyer by express mail or similar service. Typically buyers will receive their SF97 within 30 business days, although it can take up to 60 Business days, from the date the buyer takes possession of the item. Transferable titling documents typically take up to 30 business day after receipt of the SF97. Buyer is responsible for vehicle registration.
- **All bids are binding** and cannot be retracted. Failure to make full payment will result in a **Default Fee**.



SHIPPING & PICK UP DETAILS

- Buyer is **responsible for all costs** related to transporting the item.
- Item **must be picked up within 8 business days** of the auction, or the buyer will incur storage charges.

PICKUP TERMS










Failure to follow these terms may result in the seller turning away the attempt of your driver to pick up the purchased item(s).

Hours: All pickup times must be scheduled in advance with GovPlanet Customer Service.

Pickup times and requirements vary by location, all pickup times must be scheduled in advance with GovPlanet Customer Service.

Loading Dock NOT Available

Ramps NOT Available

DESCRIPTION	RATING	DETAILS
Emission Certification Label		Exempt 
Oil Pump/Tach Drive (behind doghouse cover)		
Blow by @ idle (subjective observation)		No noticeable vapor or pressure 
Starter		
Fuel System		Operational 
Exhaust System		
Radiator		
Oil Leaks		None seen
Fuel Leaks		None seen
Cooling System Leaks		None seen
Engine - Right Side		
Engine - Left Side		
Limited Function Check		The engine started and ran.
Engine #1		
 (8)		
DRIVETRAIN		

Forklift Available

Driver **MUST** bring a copy of the IronPlanet Item Release to pick the item up.

QUESTIONS

Customer Care Agents are available Monday to Friday,
6 a.m. to 5 p.m. (Pacific Time)

Phone 888-433-5426
+1-925-225-8600 (outside U.S.)

Fax 888-433-3467
+1-925-225-8610 (outside U.S.)

Email CustomerCare@ironplanet.com

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.



DESCRIPTION	RATING	DETAILS
Transmission		
Transfer Case		
Steer Axle		
Rear Drive Axle		
Limited Function Check		The drivetrain was operational.




(8)

CHASSIS

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

DESCRIPTION	RATING	DETAILS
Steering Linkage		
Frame Condition		
Limited Function Check		The main chassis components functioned during a limited check.

Tire Condition		
Wheel Condition		
Wheel Studs, Nuts, Lugs		



(7)

LOGISTICS

DESCRIPTION	RATING	DETAILS
Shipping Dimensions - DLA		Length: 180"; Width: 86"; Height: 72"
Machine Weight - DLA		Machine weight: 8,200 lb. GVWR

Disputes:

This item is offered with **IronClad Assurance®** protection. With IronClad Assurance®, if a buyer discovers that the item is not substantially in the condition as represented in this inspection report, the buyer may submit a written dispute claim to IronPlanet. Following submission of a written dispute claim, IronPlanet will investigate the claim, re-inspecting the equipment item as necessary, and determine a fair and mutually beneficial resolution. Please note that IronPlanet inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

 **Need help?** [Contact Us](#)

 **North America**  **English** 

Company[About IronPlanet](#)[About Ritchie Bros.](#)[Careers](#)[Blog](#)[Terms & Conditions](#)[Privacy](#)[Site Map](#)**Support**[Contact Us](#)[How to buy](#)[How to sell](#)[FAQs](#)[RitchieSpecs](#)**Our family of sites**[GovPlanet](#)[TruckPlanet](#)[Asset Appraisal Services](#)[Kruse Energy](#)[Ritchie Bros. Auctioneers](#)[SalvageSale](#)[Mascus](#)**Popular categories**[Truck Tractors](#)[Crawler Dozers](#)[Dump Trucks](#)[Equipment Trailers](#)[Excavators](#)[Agricultural Tractors](#)[Flatbed Trucks](#)**Stay connected****Download Our Mobile App**

Copyright © 1999-2019 IronPlanet, Inc. All Rights Reserved. IronPlanet®, Asset Appraisal ServicesSM, TruckPlanet®, GovPlanet®, Kruse EnergySM, IronClad Assurance® and Auctions you can trust® are service marks of IronPlanet, Inc. All other marks and brands are the property of their respective owners.